

■移動ブロック—ステアリングの値とスピードの関係

ステアリング	スピード		ロボット（車）の動き
	左	右	
100 	-100	-100	右まわりに 超信地旋回
90 	-100	10	右へ曲がる
80 	-100	20	
70 	-100	30	
60 	-100	40	
50 	-100	50	
40 	-100	60	
30 	-100	70	
20 	-100	80	
10 	-100	90	
0 	-100	100	直進
-10 	-90	100	左へ曲がる
-20 	-80	100	
-30 	-70	100	
-40 	-60	100	
-50 	-50	100	
-60 	-40	100	
-70 	-30	100	
-80 	-20	100	
-90 	-10	100	
-100 	100	100	左まわりに 超信地旋回

※2020/01/23現在 最新バージョンのSPIKEアプリに基づく情報です。

※仕様はアプリのアップデートによって変更される場合があります。

(2020/01/23現在)